10

5

ABSTRACT OF THE DISCLOSURE

A variety of cutout surfaces are formed on trunnions by cutting out parts of a spherical surface of each of the trunnions, to which no torque is applied. The cutout surfaces comprise a pair of opposite flat surface sections, bores, recesses or wide flat surfaces, and curved surface sections, for example.